


EF2 Tornado Damage near Harbine/Diller, Nebraska

A National Weather Service storm damage survey team found that EF2 tornado damage occurred near Harbine, Nebraska. This tornado created considerable damage to several buildings, grain bins, power lines and farm pivots. Preliminary findings indicate the tornado started southeast of Jansen and dissipated near Beatrice. Some home damage occurred, however this damage was minor and was confined to a few broken windows and torn off shingles. Below is a map of where tornado damage was found.





Grain bin pushed off its base 1.5 miles south of Harbine.



Machinery building damaged 2.5 miles southeast of Harbine.



Building destroyed near Harbine.



2 X 4's jammed into ground near Harbine.